Туре	#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	Er ro rs
, H	17		(("4375630") or ("3793603") or ("5144531") or ("3453579") or ("3693128") or ("3713065") or ("3715698")).PN.	USPA	2003/11/2 5 10:06			0
	L2	13	fuses and (coolant same conduits)	USPA	2003/11/2 5 10:32			0
	Г.3	[H	(("1323698") or ("3453579") or ("23665348") or ("3251968") or ("3116389") or ("3011038") or ("2871314") or ("2758175") or ("1919743") or ("1841686")).PN.	‡	2003/11/2 5 10:10			0
	L4	432	fuses and (coolant)	USPA T	2003/11/2 5 10:18			0
	L5	419	4 not 2	USPA T	2003/11/2 5 10:11			0
	9T	5	fuses and (coolant)	JPO	2003/11/2 5 10:18			0
	L7	П	fuses and (coolant)	EPO	2003/11/2 5 10:20			0
	L8	20	fuses and (coolant)	DERW ENT	2003/11/2 5 10:29			0
	L9	0	DE-1948030-\$.did.	EPO	2003/11/2 5 10:29			0
	L10	0	DE-01948030-\$.did.	EPO	2003/11/2 5 10:29			0
}	L11	0	DE-948030-\$.did.	EPO	2003/11/2 5 10:30			0

Type	# 1	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition
BRS	L12	0	DE-0948030-\$.did.	EPO	2003/11/2 5 10:30		
BRS	L13	0	DE-1948030-\$.did.	EPO	2003/11/2 5 10:30		
BRS	L14	Н	DE-1948030-\$.did.	EPO; DERW ENT	2003/11/2 5 10:30		
BRS	L15	0	FR-0022652-\$.did.	EPO; DERW ENT	2003/11/2 5 10:31		
BRS	L16	0	FR-0050437-\$.did.	EPO; DERW ENT	2003/11/2 5 10:31		
BRS	L17	0	FR-00050437-\$.did.	EPO; DERW ENT	2003/11/2 5 10:31		
BRS	L18	0	FR-050437-\$.did.	EPO; DERW ENT	2003/11/2 5 10:31		
BRS	L19	Н	fuses and (liguid same cooling)	USPA T	2003/11/2 5 10:32		
BRS	L20	430	fuses and (fluid same USPA cooling)	USPA T	2003/11/2 5 10:42		
IS&R	1.21	4	(("2871314") or ("2809254") or ("3562691") or ("3453579")).PN.	USPA T	USPA 2003/11/2 T 5 10:42		

면 다 아 다 양